

ANIAK AIRPORT

Contents:

- A Pavement Strength Form showing project history, latest Pavement Condition Index (PCI) data, pavement strength ratings (if available) and other useful information
- A Pavement Condition Survey – PCI Sample Unit Layout Plan
- PCI maps showing as-measured and predicted pavement conditions
- Age map showing pavement age as of 2003
- A Branch PCI Condition Report

Airport Information:

- Location: The Aniak Airport is located on the Kuskokwim River in Southwest Alaska. It is approximately 120 air miles northeast of Bethel.
- District: Southwest, Central Region
- Airport Manager: Terry Hoffman
- District Maintenance Manager: Vacant
- Pavement Surface: Asphalt Concrete, two Tar Sealed areas on Apron
- Last Pavement Construction:
 - 1997
- Pavement layout: Runway 10-28, Taxiway A and Apron
- Design Aircraft: B-737 200
- 2001 Enplanements: 16,963
- Airport Class: Primary
- Last pavement condition survey: May 30, 2003
- Next planned pavement condition survey: 2006
- 2003 reported pavement maintenance and/or changed conditions:
 - Crack sealing on runway

Recommendations:

- Continue crack sealing and patching